

DOCUMENTATION

Provide CD's, Lease Exhibits, RFDS & equipment specs to Raycap sales team.

STEP 02



INITIATE THERMAL ANALYSIS


Using information from steps 1 and 2.

STEP 04



DESIGN
Move to design & engineering phase of project.

STEP 06



STEP 01



FIT-UP
Raycap will complete equipment fit and identify pinch points.

STEP 03



THERMAL ANALYSIS RESULTS

If results pass, move to step 5.

if not...

...further evaluation of equipment positioning, location, concealment size, fans, etc. will be incorporated to achieve a passing result.

STEP 05



FABRICATE
Begin concealment fabrication.